





Sep.1.2019 Copyright 2019 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.




1 FIGURE OF INSERTION


HORIZONTALLY ○

DF57H-2S-1.2C

DIAGONAL ×



NOTE 1 AVOID ANGLED INSERTION OF CRIMP CONTACT(DF57-***SCF) TO MAINTAIN PERFORMANCE RELIABILITY.


			1		PBT		UL94V-0, NATURAL(WHITE)											
NO.		MATERIAL		FINISH , REMARKS			NO.		MATERIAL		FINISH , REMARKS							
UNITS mm				SCALE 20 : 1				COUNT		DESCRIPTION OF REVISIONS			DESIGNED		CHECKED		DATE	
 HIROSE ELECTRIC CO., LTD.				APPROVED : KI. AKIYAMA				12. 03. 19		DRAWING NO.		EDC3-343900-00						
				CHECKED : HK. UMEHARA				12. 03. 19		PART NO.		DF57H-2S-1. 2C						
				DESIGNED : TS. KUMAZAWA				12. 03. 19		CODE NO.		CL666-0100-6-00						
				DRAWN : TS. KUMAZAWA				12. 03. 19				 1/2						

Sep.1.2019 Copyright 2019 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.


DF57 Series Mating / Unmating Operation Instruction

Mating


①By positioning the convexity of the socket sides to the header concavity, align the centers of the socket and the header in pitch direction.



②Slightly press the socket down at cable side to tilted angle.




③Press down at the lever side with stabilizing the cable side to insert. Mating completes.




Unmating


①Hook the lever with finger nail.



②Lift up to the upper direction and friction lock is released.



③Lift up to the upper direction and positive lock is released. Removal completes.



HRS DRAWING FOR REFERENCE

HRS

DRAWING NO.	EDC3-343900-00
PART NO.	DF57H-2S-1.2C
CODE NO.	CL666-0100-6-00

△ 2/2